

## Digital temperature and humidity meter DTM-303A

New



### Features:

- ※ Large digital LCD display, easy to read.
- ※ Can display indoor temperature and humidity, and outdoor temperature.
- ※ °C or °F temperature display can be selected immediately.
- ※ Maximum and minimum temperature and humidity memory function.
- ※ Temperature measurement range is -10°C to +50°C; its resolution is 0.1°C.
- ※ Outdoor measurement range is -50°C to +70°C; its resolution is 0.1°C (3 meters long white line).
- ※ Humidity measurement range is 20~100%; its resolution is 1%.

### Key Description:

ON/OFF: Turn the power on and off.

°C/°F: Switch between Celsius and Fahrenheit display.

MAX/MIN: Maximum/minimum temperature and humidity display.

IN/OUT: Indoor (IN) or outdoor (OUT) temperature display.

### DTM-303A Operation Manual

Installation and battery replacement:

1. Open the battery cover (under the rear panel).
2. Insert the "AAA" (1.5V battery) and install it according to the instructions on the battery holder (+ and -).
3. Close the battery cover.

Measurement of temperature and humidity:

※ This unit can continuously measure temperature and humidity unless other functions are set.

※ You can choose °C or °F temperature display according to your needs show:

※ The lower part of the thermometer screen displays temperature, and the upper part displays humidity.

※ Users can press the MAX/MIN key to view the records of the maximum and minimum values of temperature and humidity.

Record of maximum and minimum temperature and humidity:

※ When the current temperature and humidity are displayed, pressing the MAX/MIN key will display the maximum value of temperature and maximum value of humidity.